

Oil Field Environmental Incident Summary

Incident: 20130825171924 **Date/Time of Notice:** 08/25/2013 17:09

Responsible Party: OXY USA Inc.

Well Operator: OXY USA INC.

Well Name: STATE 3-16-21H-143-96

Field Name: FAYETTE

Well File #: 23028

Date Incident: 8/25/2013 **Time Incident:** 0800

Facility ID Number:

County: DUNN

Twp: 143

Rng: 96

Sec: 9

Qtr: SW SW

Location Description:

Submitted By: Terry Ryland

Received By:

Contact Person: Terry Ryland
5 GREENWAY PLAZA STE 110
HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	70	barrels	50	barrels	70	barrels
Brine	70	barrels	50	barrels	50	barrels
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 10/27/2014 **Clean Up Concluded:** 10/7/2013

Risk Evaluation:

Low due to presence of salts and oil on surface soil outside of containment.

Areal Extent:

Well pad and adjacent to well pad off location

Potential Environmental Impacts:

Impacted soil.

Action Taken or Planned:

OXY contracted Baranko Brothers to respond to the incident and stabilize the situation. Multiple pump trucks were on location to draw fluids from the diked areas. Trucks were brought in to lower the tank levels. Weston Solutions will work with Baranko Brothers to remove all contaminated soil and truck to Chimney Butte. Profile and manifesting already generated. Samples will be taken to confirm clean. Oxy is contacting adjacent landowner to notify of the situation. Monday will be the day to begin the soil remediation and return the site to its original condition.

Wastes Disposal Location: Chimney Butte Landfill.

Agencies Involved:

Updates

Date: 8/26/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Off location impact. Follow-up is necessary. Determine off location land use, and forward updates to Dr. Keller if land use is pasture or hay crop.

Date: 8/30/2013 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

N.) 47.214944
W.) -102.862278

Arrived on location at 3:18 pm CST 8/30/2013.

Site yet to be cleaned up at time of inspection. Water in puddle off of location is impacted with oil and brine testing at 2.60 millisiemens. Impacted area is a pasture currently vacant.

Follow Up inspection required.

Date: 7/16/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 7/16/2014.

Second inspection at location shows no signs of original impact on areas off of the well pad.

Remediation considered complete. No followup is necessary.